



LCD



Note: the remaining AND gate in the 74HC32 can be used here. I opted to use two NOT gates from a spare 74HC04 because I had some problems with the image and could not determine if the clock signal was causing interference within the chip itself.

TITLE: Design 2	
Document Number:	REV:
Date: 6/18/2007 05:47:19p	Sheet: 1/1